

# 6HP-VBR-WT (With Tools)

VB Repair Kit – Solenoid & Lube Regulator

## Prevents-Corrects-Reduces

Persistent Coast-down Clunk Hot, Ratio Codes, Long slip-sliding shifts hot. Premature Bushing Failure (more common on HP21's) and Ford 6R60 75 & 80 series with 42-46 mph TCC "Quiver".

Need a parts only Re-Fill?  
Order **6HP-VBR-NT**

There are many model specific differences!

Re-assemble your model as you found it.




Product Support (626) 443-7451


**Fits: 1st & 2nd Type VB's ONLY!**  
Ford 6R60 & 80 Series  
ZF6HP-26, 21 & 19 Series

## I.D. The Valve Body First!

Type 1



Type 2



Type 3

