

We released a few kits with the (2) two gaskets swapped in the picture. Picture below is correct and should be used to replace page 3 in SK 6F35 kit instructions. We apologize for any inconvenience that may occur. Please feel free to call our techs for assistance with this matter (626) 443-7451.

READ THIS: SK 6F35 Main Plate & Gaskets fit 2009-2013½ Models that do not have any dampeners (See page 4) located in the Solenoid Body.

If working on 2013½ & up models: Re-use your original front plate if okay.

Step 1

Original 2009 –2013 ½ Main Plate is usually damaged at check ball locations.
New 2009-2013½ Updated Replacement plate and VB gaskets are provided.

Note: Updated plate is designed to work WITH this kit and is marked “SK 6F35”

DO NOT ATTEMPT to use new Updated plate on any 2009 to 2013½ without installing the entire kit.

